



- 5, 23" Culvert Pipes

- Undercutting by recent (2013) heavy rain will require repairing

- GPS Location N 37° 50.264'
W 079° 46.538'